




KEY TO STATIONING

NOTE:  
Original Bad Rock should be inspected when uncovered and the surface generally removed to an average depth of 12 inches. If the rock is found to be of good quality, it may be left in place. If the rock is found to be of poor quality, it should be removed. The base of the dam should be higher than EL. 36.0 in Area under Block V.

SECTION 17 F, DOWNSTREAM FROM AXIS OF DAM

LOOKING UPSTREAM  
SCALE 1" = 40'-0"

|                                                                  |                  |                                            |          |
|------------------------------------------------------------------|------------------|--------------------------------------------|----------|
| EONNEVILLE PROJECT                                               |                  | CONTRACT NO. 100-100                       |          |
| SECTION 17 F, DOWNSTREAM FROM AXIS OF DAM - SOUTH LIMIT SP. 4.5. |                  | R.Y. R/W LINE TO PIER W-4                  |          |
| U. S. ENGINEER CORPS, DISTRICT OF COLUMBIA                       |                  | U. S. ENGINEER CORPS, DISTRICT OF COLUMBIA |          |
| NO.                                                              | REVISION         | DATE                                       | BY       |
| 1                                                                | Original         | 6-1-12                                     | W. J. B. |
| 2                                                                | Removed Bad Rock | 6-1-12                                     | W. J. B. |
| 3                                                                | Added Bad Rock   | 6-1-12                                     | W. J. B. |

6-1-12

SHEET NO 7 of

M-5-12