

Fish Conditon Weekly Report #23-01

Project Biologist: Rick Martinson

Welcome to the 2023 Northern Wasco County PUD fish condition monitoring season. Passage conditions through the dewatering structure are monitored by collecting all bypassed fish for 24 hours once a week, April through July. The fish collected are examined for injuries and if none are found, it's assumed conditions are favorable. The first samples, before spill starts, are dominated by subyearling Chinook fry. The number of fry in this sample exceeded the season total fry collected in all but two years.

Section 2. River Conditions (for the 24 hour sample period)



NORTHERN
WASCO
COUNTY
PUD
PEOPLE'S UTILITY DISTRICT

[illegible]

Section 4. Incidental Catch

Date	Mortality																												Totals													
	Crappie	Morts	Bullhead	Mort	Bass	Mort	Catfish	Mort	Mountain Whitesih	mort	Bluegill	Mort	Lamprey-Ad	Mort	Lamprey-Pac Amo	Mort	Lamprey-Pac Mac	Mort	Mysid shrimp	mort	N Pikemimow	Mort	Peamouth	Mort	Perch	mort	Siberian Prawn	Mort	Sculpin	Mort	American Shad	Mort	Walleye	Mort	Sucker	Mort	Banded Killifish	Mort	TOTAL GOOD	Total Mort	Grand Total	
5-Apr															13															2										15	0	15
12-Apr																																								0	0	0
19-Apr																																								0	0	0
26-Apr																																								0	0	0
3-May																																								0	0	0
10-May																																								0	0	0
17-May																																								0	0	0
24-May																																								0	0	0
31-May																																								0	0	0
7-Jun																																								0	0	0
14-Jun																																								0	0	0
21-Jun																																								0	0	0
29-Jun																																								0	0	0
5-Jul																																								0	0	0
12-Jul																																								0	0	0
19-Jul																																								0	0	0
26-Jul																																								0	0	0
Sub Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	13	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	15	0	15	
Total	0		0		0		0		0		0		0		13		0		0		0		0		0		0		2		0		0		0		0					

Section 5. Detailed Condition Data

Nothing to report.

Section 6. Pictures



Pictured here are the collection tank and the discharge point on the downstream end of the dewatering screen.