

FPP Change Form

Change Request Number: 09BON006

Date: 9/11/08

Proposed by: FPOM

Location of Change: BON 2.1.2

Proposed Change: Include, at the end of the paragraph, “Turbine units should be operated at the mid or upper 1% range whenever possible, during the split flows operation.”

Reason for Change: Without this guidance, the Control Room will allow GDACS to run the units, which may result in some units operating at the lower end of the 1% band.

Comments from others:

Record of Final Action: Approved at the 04 December FPOM meeting.