

MEMORANDUM FOR THE RECORD – 20 LGS 13 Orifice Lights Out of Service

SUBJECT: On July 1, Environmental Assessment Services (EAS) staff conducting the daily juvenile fish inspection found all of the lights on the 8th floor of the powerhouse were off. This included all of the attraction lights for the orifices. Upon further investigation, the contractor conducting the telecommunications installation was allowed to remove a panel from service for safe installation. Orifice lights were turned off from 10:00 through 11:50.

In accordance to the Fish Passage Plan, Little Goose must ensure orifice lights are operational on open orifices 24 hours a day (Chapter 8, 2.3.2.4.).

Additional telecommunications work was conducted on July 06, but no power outages were required. The power portion of the telecommunications install is complete and no further power outages are anticipated.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures – N/A.
- H. Pictures – N/A

Sincerely,
Scott St. John
Project Biologist
Little Goose Dam
(509) 399-2233 ext. 263
Scott.St.John@usace.army.mil